UL Mark Surveillance Flowchart

Field engineer meets with customer contact at the manufacturing location

↓

Walk through of facility is conducted

↓

Conduct review of documentation needed to perform surveillance visit

↓

UL Solutions labeled or intended to be labeled product is identified — **NO** → Production Ready (PRV) Report is issued

YES

↓

Inspection of selected product to FUS Requirements begins

↓

- Label records and production records are reviewed

  [Link to Label Center](#)

- Product attributes are verified and measurements taken when applicable

  [Link to resources](#)

- Required tests are witnessed

  [Link to resources](#)

- Traceability of Parts is verified

  [Link to resources](#)

- Calibration of IMTE verified

  [Link to resources](#)

↓

Compliance to Requirements? — **NO** → Nonconformance Report Issued

[Link to resources](#)

YES

↓

Inspection Report Issued

[Link to resources](#)

↓

Inspection Concludes

Additional resources:
[UL Product IQ](#)
[Link to MyUL Portal](#)

For more information please contact your local UL Solutions field engineering team.